

Bulletin | Danfoss TurboCor Compressors

# Customer Notification

B-CN-286-EN Rev A

August 3, 2022

**SUBJECT: Bearing Sensor Cables Improvement**

## Purpose

---

This purpose of this bulletin is to notify customers of a product improvement of the bearing sensor cables for TTS/TGS and TTH/TGH compressors.

## Summary

---

### Improvement

A design change to the bearing sensor cables was implemented to ensure uniformity in the plating.

This upgrade was part of our continuous improvement process to modernize our components and to improve the signal integrity and reliability between the sensor rings and the backplane.

### Part numbers

Compressors and Bearing sensor cable kits shipped on and after December 2, 2021, have the latest design change implemented.

Part numbers did not change:

- 100064 - CABLE HARNESS FRONT BEARING SENSOR
- 100065 - CABLE HARNESS REAR BEARING SENSOR

## Action Required

---

N/A

## Need Assistance

---

For further technical questions, please contact [Turbocor.PS.NA@Danfoss.com](mailto:Turbocor.PS.NA@Danfoss.com). For any other related questions, please contact your Key Account Manager.